


FIG. 1 (PRIOR ART)






FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 4D




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 5D




FIG. 5E





FIG. 5F






FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D




FIG. 7E





FIG. 7F






FIG. 9A




FIG. 9B




FIG. 9C




FIG. 10A




FIG. 10B




FIG. 10C




FIG. 11




FIG. 12




FIG. 13A




FIG. 13B




FIG. 14

FIG. 15A




FIG. 15B




FIG. 15C





FIG. 15D






FIG. 18




FIG. 19B




FIG. 19C




FIG. 20A




FIG. 20B




FIG. 20C




FIG. 20D






FIG. 20E






FIG. 21




FIG. 22A




FIG. 23A




FIG. 22B




FIG. 23B




FIG. 22C




FIG. 24A




FIG. 24B




FIG. 24C




FIG. 24D




FIG. 24E




FIG. 24F

FIG. 25A




FIG. 25B




FIG. 25C








FIG. 25D





$$NA \cdot WA = ND1 \cdot WD1 + ND2 \cdot WD2$$

FIG. 26






FIG. 28B

FIG. 29




FIG. 30











FIG. 31








FIG. 36A




FIG. 36B




FIG. 36C




FIG. 36D






FIG. 38A




FIG. 38B





FIG. 38C






FIG. 39




FIG. 40A




FIG. 40B




FIG. 40C




FIG. 40D




FIG. 41A




FIG. 41B




FIG. 42A

FIG. 42B




FIG. 43A

FIG. 43B




FIG. 44




FIG. 45




FIG. 46A




FIG. 46B





FIG. 46C






FIG. 49A




FIG. 49B

FIG. 50A




FIG. 50B




FIG. 51




FIG. 52

